

CERTIFICATE OF COMPLIANCE

Certificate Number 20170627-E160453
Report Reference E160453-19940125
Issue Date 2017-JUNE-27

Issued to: ROCKWELL AUTOMATION INC
Drives Business
6400 W ENTERPRISE DR
Mequon, WI 53092 USA

This is to certify that representative samples of Motors - Component
See Addendum Page for Models

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-1 - Rotating Electrical Machines - General Requirements

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170627-E160453
Report Reference E160453-19940125
Issue Date 2017-JUNE-27

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Servo motors, Models 1326AB-A1E-11, 1326AB-A1G-11, 1326AB-A2E-11, 1326AB-A2G-11, 1326AB-A3E-11, 1326AB-A3G-11, 1326AB-B1C-11, 1326AB-B1E-11, 1326AB-B2C-11, 1326AB-B2E-11, 1326AB-B3C-11, 1326AB-B3E-11, 1326AB-B4C-11, 1326AB-B4E-11, 1326AB-C1C-11, 1326AB-C1E-11, 1326AB-C2C-11, 1326AB-C2E-11, 1326AB-C3C-11, 1326AB-C3E-11, 1326AB-C4B-11, 1326AB-C4C-11, 1326AB-A1E-11-A4, 1326AB-A1G-11-A4, 1326AB-A2E-11-A4, 1326AB-A2G-11-A4, 1326AB-A3E-11-A4, 1326AB-A3G-11-A4, 1326AB-B1C-11-A5, 1326AB-B1E-11-A5, 1326AB-B2C-11-A5, 1326AB-B2E-11-A5, 1326AB-B3C-11-A5, 1326AB-B3E-11-A5, 1326AB-B4C-11-A5, 1326AB-B4E-11-A5, 1326AB-C1C-11-A7, 1326AB-C1E-11-A7, 1326AB-C2C-11-A7, 1326AB-C2E-11-A7, 1326AB-C3C-11-A7, 1326AB-C3E-11-A7, 1326AB-C4B-11-A7, 1326AB-C4C-11-A7, 1326AB-A1E-11-K4, 1326AB-A1G-11-K4, 1326AB-A2E-11-K4, 1326AB-A2G-11-K4, 1326AB-A3E-11-K4, 1326AB-A3G-11-K4, 1326AB-B1C-11-K5, 1326AB-B1E-11-K5, 1326AB-B2C-11-K5, 1326AB-B2E-11-K5, 1326AB-B3C-11-K5, 1326AB-B3E-11-K5, 1326AB-B4C-11-K5, 1326AB-B4E-11-K5, 1326AB-C1C-11-K7, 1326AB-C1E-11-K7, 1326AB-C2C-11-K7, 1326AB-C2E-11-K7, 1326AB-C3C-11-K7, 1326AB-C3E-11-K7, 1326AB-C4B-11-K7, 1326AB-C4C-11-K7, 1326AB-A1E-21, 1326AB-A1G-21, 1326AB-A2E-21, 1326AB-A2G-21, 1326AB-A3E-21, 1326AB-A3G-21, 1326AB-B1C-21, 1326AB-B1E-21, 1326AB-B2C-21, 1326AB-B2E-21, 1326AB-B3C-21, 1326AB-B3E-21, 1326AB-B4C-21, 1326AB-B4E-21, 1326AB-C1C-21, 1326AB-C1E-21, 1326AB-C2C-21, 1326AB-C2E-21, 1326AB-C3C-21, 1326AB-C3E-21, 1326AB-C4B-21, 1326AB-C4C-21, 1326AB-A1E-21-A4, 1326AB-A1G-21-A4, 1326AB-A2E-21-A4, 1326AB-A2G-21-A4, 1326AB-A3E-21-A4, 1326AB-A3G-21-A4, 1326AB-B1C-21-A5, 1326AB-B1E-21-A5, 1326AB-B2C-21-A5, 1326AB-B2E-21-A5, 1326AB-B3C-21-A5, 1326AB-B3E-21-A5, 1326AB-B4C-21-A5, 1326AB-B4E-21-A5, 1326AB-C1C-21-A7, 1326AB-C1E-21-A7, 1326AB-C2C-21-A7, 1326AB-C2E-21-A7, 1326AB-C3C-21-A7, 1326AB-C3E-21-A7, 1326AB-C4B-21-A7, 1326AB-C4C-21-A7, 1326AB-A1E-21-K4, 1326AB-A1G-21-K4, 1326AB-A2E-21-K4, 1326AB-A2G-21-K4, 1326AB-A3E-21-K4, 1326AB-A3G-21-K4, 1326AB-B1C-21-K5, 1326AB-B1E-21-K5, 1326AB-B2C-21-K5, 1326AB-B2E-21-K5, 1326AB-B3C-21-K5, 1326AB-B3E-21-K5, 1326AB-B4C-21-K5, 1326AB-B4E-21-K5, 1326AB-C1C-21-K7, 1326AB-C1E-21-K7, 1326AB-C2C-21-K7, 1326AB-C2E-21-K7, 1326AB-C3C-21-K7, 1326AB-C3E-21-K7, 1326AB-C4B-21-K7, 1326AB-C4C-21-K7, 1326AB-C2F-11-G3, 1326AB-A410E-21, 1326AB-A415E-21, 1326AB-A420E-21, 1326AB-A425E-21, 1326AB-A430E-21, 1326AB-A410E-21-K4, 1326AB-A415E-21-K4, 1326AB-A420E-21-K4, 1326AB-A425E-21-K4, 1326AB-A430E-21-K4, 1326AB-A410E-21-A4, 1326AB-A415E-21-A4, 1326AB-A420E-21-A4, 1326AB-A425E-21-A4, 1326AB-A430E-21-A4, 1326AB-A410G-21, 1326AB-A415G-21, 1326AB-A420G-21, 1326AB-A425G-21, 1326AB-A430G-21, 1326AB-A410G-21-K4, 1326AB-A415G-21-K4, 1326AB-A420G-21-K4, 1326AB-A425G-21-K4, 1326AB-A430G-21-K4, 1326AB-A410G-21-A4, 1326AB-A415G-21-A4, 1326AB-A420G-21-A4, 1326AB-A425G-21-A4, 1326AB-A430G-21-A4, 1326AB-A510C-21, 1326AB-A515C-21, 1326AB-A520C-21, 1326AB-A525C-21, 1326AB-A530C-21, 1326AB-A535C-21, 1326AB-A540C-21, 1326AB-A510C-21-K5, 1326AB-A515C-21-K5, 1326AB-A520C-21-K5, 1326AB-A525C-21-K5, 1326AB-A530C-21-K5, 1326AB-A535C-21-K5, 1326AB-A540C-21-K5, 1326AB-A510C-21-A5, 1326AB-A515C-21-A5, 1326AB-A520C-21-A5, 1326AB-A525C-21-A5, 1326AB-A530C-21-A5, 1326AB-A535C-21-A5, 1326AB-A540C-21-A5, 1326AB-A510E-21, 1326AB-A515E-21, 1326AB-A520E-21, 1326AB-A525E-21, 1326AB-A530E-21, 1326AB-A535E-21, 1326AB-A540E-21, 1326AB-A510E-21-K5, 1326AB-A515E-21-K5, 1326AB-A520E-21-K5, 1326AB-A525E-21-K5, 1326AB-A530E-21-K5, 1326AB-A535E-



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170627-E160453
Report Reference E160453-19940125
Issue Date 2017-JUNE-27

21-K5, 1326AB-A540E-21-K5, 1326AB-A510E-21-A5, 1326AB-A515E-21-A5, 1326AB-A520E-21-A5, 1326AB-A525E-21-A5, 1326AB-A530E-21-A5, 1326AB-A535E-21-A5, 1326AB-A540E-21-A5, 1326AB-A710C-21, 1326AB-A715C-21, 1326AB-A720C-21, 1326AB-A725C-21, 1326AB-A730C-21, 1326AB-A740C-21, 1326AB-A710C-21-K7, 1326AB-A715C-21-K7, 1326AB-A720C-21-K7, 1326AB-A725C-21-K7, 1326AB-A730C-21-K7, 1326AB-A735C-21-A7, 1326AB-A740C-21-K7, 1326AB-A710C-21-A7, 1326AB-A715C-21-A7, 1326AB-A720C-21-A7, 1326AB-A725C-21-A7, 1326AB-A730C-21-A7, 1326AB-A735C-21-A7, 1326AB-A740C-21-A7, 1326AB-A710E-21, 1326AB-A715E-21, 1326AB-A720E-21, 1326AB-A725E-21, 1326AB-A730E-21, 1326AB-A735E-21, 1326AB-A740E-21, 1326AB-A710E-21-K7, 1326AB-A715E-21-K7, 1326AB-A720E-21-K7, 1326AB-A725E-21-K7, 1326AB-A730E-21-K7, 1326AB-A735E-21-K7, 1326AB-A740E-21-K7, 1326AB-A710E-21-A7, 1326AB-A715E-21-A7, 1326AB-A720E-21-A7, 1326AB-A725E-21-A7, 1326AB-A730E-21-A7, 1326AB-A735E-21-A7, 1326AB-A740E-21-A7, 1326AB-B410E-21, 1326AB-B415E-21, 1326AB-B420E-21, 1326AB-B425E-21, 1326AB-B430E-21, 1326AB-B410E-21-K4, 1326AB-B415E-21-K4, 1326AB-B420E-21-K4, 1326AB-B425E-21-K4, 1326AB-B430E-21-K4, 1326AB-B410E-21-A4, 1326AB-B415E-21-A4, 1326AB-B420E-21-A4, 1326AB-B425E-21-A4, 1326AB-B430E-21-A4, 1326AB-B410G-21, 1326AB-B415G-21, 1326AB-B420G-21, 1326AB-B425G-21, 1326AB-B430G-21, 1326AB-B410G-21-K4, 1326AB-B415G-21-K4, 1326AB-B420G-21-K4, 1326AB-B425G-21-K4, 1326AB-B430G-21-K4, 1326AB-B410G-21-A4, 1326AB-B415G-21-A4, 1326AB-B420G-21-A4, 1326AB-B425G-21-A4, 1326AB-B430G-21-A4, 1326AB-B510C-21, 1326AB-B515C-21, 1326AB-B520C-21, 1326AB-B525C-21, 1326AB-B530C-21, 1326AB-B535C-21, 1326AB-B540C-21, 1326AB-B510C-21-K5, 1326AB-B515C-21-K5, 1326AB-B520C-21-K5, 1326AB-B525C-21-K5, 1326AB-B530C-21-K5, 1326AB-B535C-21-K5, 1326AB-B540C-21-K5, 1326AB-B510C-21-A5, 1326AB-B515C-21-A5, 1326AB-B520C-21-A5, 1326AB-B525C-21-A5, 1326AB-B530C-21-A5, 1326AB-B535C-21-A5, 1326AB-B540C-21-A5, 1326AB-B510E-21, 1326AB-B515E-21, 1326AB-B520E-21, 1326AB-B525E-21, 1326AB-B530E-21, 1326AB-B535E-21, 1326AB-B540E-21, 1326AB-B510E-21-K5, 1326AB-B515E-21-K5, 1326AB-B520E-21-K5, 1326AB-B525E-21-K5, 1326AB-B530E-21-K5, 1326AB-B535E-21-K5, 1326AB-B540E-21-K5, 1326AB-B510E-21-A5, 1326AB-B515E-21-A5, 1326AB-B520E-21-A5, 1326AB-B525E-21-A5, 1326AB-B530E-21-A5, 1326AB-B535E-21-A5, 1326AB-B540E-21-A5, 1326AB-B710C-21, 1326AB-B715C-21, 1326AB-B720C-21, 1326AB-B725C-21, 1326AB-B730C-21, 1326AB-B735C-21, 1326AB-B740C-21, 1326AB-B710C-21-K7, 1326AB-B715C-21-K7, 1326AB-B720C-21-K7, 1326AB-B725C-21-K7, 1326AB-B730C-21-K7, 1326AB-B735C-21-K7, 1326AB-B740C-21-K7, 1326AB-B710C-21-A7, 1326AB-B715C-21-A7, 1326AB-B720C-21-A7, 1326AB-B725C-21-A7, 1326AB-B730C-21-A7, 1326AB-B735C-21-A7, 1326AB-B740C-21-A7, 1326AB-B710E-21, 1326AB-B715E-21, 1326AB-B720E-21, 1326AB-B725E-21, 1326AB-B730E-21, 1326AB-B735E-21, 1326AB-B740E-21, 1326AB-B710E-21-K7, 1326AB-B715E-21-K7, 1326AB-B720E-21-K7, 1326AB-B725E-21-K7, 1326AB-B730E-21-K7, 1326AB-B735E-21-K7, 1326AB-B740E-21-K7, 1326AB-B710E-21-A7, 1326AB-B715E-21-A7, 1326AB-B720E-21-A7, 1326AB-B725E-21-A7, 1326AB-B730E-21-A7, 1326AB-B735E-21-A7, 1326AB-B740E-21-A7, 1326AB-B410J, 1326AB-B420H-21, 1326AB-B430G-21, 1326AB-B515G-21, 1326AB-B520F-21.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

